

Table 1. Reference (RbRs will be left CHILDLSS)

L4 id	req_key	rel	req_type	ver_method	ver_status	clarification	text	RBR_id	req_type	a_verif_method	a_verif_status	text	interpretation text	clarification
C-MSS-70482	-7840	B0	interface	test	unverified		The MSS Security Management Application Service shall have the capability to send to NOLAN, notifications of security breaches at ECS facilities that could affect NOLAN and other EOSSDIS sites.	NI-0480#B	interface	test	un-verified	ECS shall have the capability to send to NOLAN notifications of security breaches at ECS facilities that could affect NOLAN and other EOSSDIS sites.		
C-MSS-70484	-7841	B0	interface	test	unverified		The MSS Security Management Application Service shall have the capability to receive, from NOLAN, notifications of security breaches at NOLAN sites or within the NOLAN network that could potentially affect ECS sites.	NI-0470#B	interface	test	un-verified	ECS shall have the capability to receive notifications of security breaches at NOLAN sites or within the NOLAN network that could potentially affect ECS sites.		
C-MSS-66585	-12263	B0	interface	test	unverified		The MSS Performance Management Application Service shall have the capability to receive, from NOLAN, periodic information regarding NOLAN network performance and link utilization.	NI-0460#B	interface	test	un-verified	ECS shall have the capability to receive periodic information regarding EBnet network performance and link utilization.		

The change of NOLAN to EBnet causes several L4 to be invalid. Additionally, efforts are underway to update the ICD requirements which involve the deletion of NI-0460, NI-0470, and NI-0480. This would leave MSS L4s orphaned.